

This 3 in 1 soil testing tool is designed for quick and easy checking of soil through Photometer (light testing) Hydrometer (moisture testing) and a PH meter (PH level testing).

Directions for use

- Select Moisture, pH or Light as required to measure levels
- Stick the probe about 2-4 inches into the soil - making sure to avoid big stones
- Adjust the position until the pointer on the dial swings slightly
- Wait for 10 minutes to take note of the readings of Moisture, pH or Light
- Remove probe from soil and wipe clean after each use



Light Sensor

Only works in natural sunlight.

Switch

pH Sensor

The optimal pH level is between 5.5 - 7.
Dial will only move if the acidity is outside this range.

Moisture Sensor

**Measure soil Moisture, pH and Light
just by plugging in the probe!**

No batteries required!